



CONSTRUCTION UPDATES & ACTIVITIES
Week Ending June 23, 2017

San Luis Obispo Instructional Building

Work this week: The second floor exterior windows have continued to be installed. A portion of the interior aluminum frames were placed by the glazing contractor. The first floor HVAC ducting has been completed and passed inspection, and cable trays in the first floor classrooms began to be installed by the electrical contractor.

- Noise:** Some noise
- Parking:** Some permanent parking loss
- Utilities:** None
- Odors:** None
- Dust:** Moderate dust impact
- Vibrations:** Minor vibrations
- Vision:** None

